Summary of Fall 2014 Commissioning run

A. Deur Jefferson Lab

Purpose:

•Summarize the Fall 2014 run;

•Review run to identify possible improvements.



A. Deur. GlueX collaboration meeting. 02/19/2015

Fall 2014 goals

Our Goals:

- •CW beam to tagger with acceptable radiation levels.
- •Create unpolarized photon beam and tune it through:
 - •Collimators; 🗸
 - Target location;
 - •Photon beam dump.

Detectors, DAQ and trigger check out, optimization, calibration and alignment.

Key Performance Parameter (KPP) Goals:

- •Full detector running for at least 8h at 1200A, recording data from all subsystems;
- •Produce plots with coincidence of the signals in Tagx, TOF, BCal, FCal, ST, PS;
- •Event display showing correlations of hits in the CDC, FDC, ST, TOF, BCal and FCal;
- •Target position from tracking;
- •Demonstration of PID using FCal, BCal, TOF and/or other detectors.



Specifics for Fall 2014 commissioning

•CW e⁻ beam

~10.1 GeV;Nominal: 50 nA, up to 200 nA.

•Amorphous radiators: 0.2, 1.1 and 3.3 $\times 10^{-4}$ RL.

•Initially, no tagger electronics.

•Secondary collimator initially removed. Then installed.

•Various commissioning targets. Used only Icm CH₂ disk & Al. barrel targets at nominal target center (could be positioned between +12cm and -32cm) Target history: https://halldweb1.jlab.org/wiki/index.php/Target_Conditions

•Beam Profiler(s). Located either in front of active collimator or photon beam dump. Now part of standard equipment. Added one "active target" during run (first upstream of solenoid, then downstream).

•Radiation monitoring equipment (borrowed from RadCon group) + OSL for crosscalibration/neutron monitoring in Hall D.

Helpful for beam diagnostic. Will be used again for Spring run, along with new own Hall D monitors.





Run plan



Thursday, February 19, 2015

A. Deur. GlueX collaboration meeting. 02/19/2015





A. Deur. GlueX collaboration meeting. 02/19/2015

•Good radiation levels (both in tagger and Hall) once the beam is tuned. Reproducible. Standard beam delivery procedure established.

- •Rates scale with radiator thickness \Rightarrow Good photon beam. No scrapping.
- •Profiler works.Active collimator works and is calibrated.

•Transmission through collimator seemed good.

- Beam line (including target) is well aligned. Diagnostic tools checked (Upstream Profiler, Halo Counters, Active Target, Pair Spec, Start Counter).
 Solenoid ran at 1000A happily for a long time.
- All detectors worked well. Detectors triggered in coincidence. DAQ works.
 FDC alignment data (no/low B-field) taken. (Only one target position).
- •DAQ rate limited.
- •Solenoid trips.
- •Beam current drift. Photon flux in Hall varies a lot.
- •Beam position unstable.
- •Downstream Profiler did not work. Replaced by upstream one.
- •Upstream profiler(+radiator) creates large noise in Pair Spec.
- •FDC cooling system.
- •SC slightly tilted. FCal noisy. Non-expert Pair Spec. access. Event display freeze.
- •Last accelerator harps not functional.
- •Safety: unorthodox access to hall during Controlled Access.



- •Good radiation levels (both in tagger and Hall) once the beam is tuned. Reproducible. Standard beam delivery procedure established.
- •Rates scale with radiator thickness \Rightarrow Good photon beam. No scrapping.
- •Profiler works.Active collimator works and is calibrated.
- •Transmission through collimator seemed good.
- •Beam line (including target) is well aligned. Diagnostic tools checked (Upstream Profiler, Halo Counters, Active Target, Pair Spec, Start Counter).

•Solenoid ran at 1000A happily for a long time.

All detectors worked well. Detectors triggered in coincidence. DAQ works.
FDC alignment data (no/low B-field) taken. (Only one target position).

•DAQ rate limited.

•Solenoid trips.

•Beam current drift. **Photon flux in Hall varies a lot.**

•Beam position unstable.

- •Downstream Profiler did not work. Replaced by upstream one.
- •Upstream profiler(+radiator) creates large noise in Pair Spec.
- •FDC cooling system.
- •SC slightly tilted. FCal noisy. Non-expert Pair Spec. access. Event display freeze.
- •Last accelerator harps not functional.

•Safety: unorthodox access to hall during Controlled Access.



- •Good radiation levels (both in tagger and Hall) once the beam is tuned. Reproducible. Standard beam delivery procedure established.
- •Rates scale with radiator thickness \Rightarrow Good photon beam. No scrapping.
- •Profiler works.Active collimator works and is calibrated.
- •Transmission through collimator seemed good.
- Beam line (including target) is well aligned. Diagnostic tools checked (Upstream Profiler, Halo Counters, Active Target, Pair Spec, Start Counter).
 Solenoid ran at 1000A happily for a long time.
- All detectors worked well. Detectors triggered in coincidence. DAQ works.
 FDC alignment data (no/low B-field) taken. (Only one target position).

•DAQ rate limited.

- •Solenoid trips.
- •Beam current drift.

Photon flux in Hall varies a lot.

- •Beam position unstable.
- •Downstream Profiler did not work. Replaced by upstream one.
- •Upstream profiler(+radiator) creates large noise in Pair Spec.
- •FDC cooling system.
- SC slightly tilted. FCal noisy. Non-expert Pair Spec. access. Event display freeze.
 Last accelerator harps not functional.
- •Safety: unorthodox access to hall during Controlled Access.



- •Good radiation levels (both in tagger and Hall) once the beam is tuned. Reproducible. Standard beam delivery procedure established.
- •Rates scale with radiator thickness \Rightarrow Good photon beam. No scrapping.
- •Profiler works.Active collimator works and is calibrated.
- •Transmission through collimator seemed good.
- Beam line (including target) is well aligned. Diagnostic tools checked (Upstream Profiler, Halo Counters, Active Target, Pair Spec, Start Counter).
 Solenoid ran at 1000A happily for a long time.
- All detectors worked well. Detectors triggered in coincidence. DAQ works.
 FDC alignment data (no/low B-field) taken. (Only one target position).

•DAQ rate limited.

- •Solenoid trips.
- •Beam current drift.

Photon flux in Hall varies a lot.

- •Beam position unstable.
- •Downstream Profiler did not work. Replaced by upstream one.
- •FDC cooling system.
- •SC slightly tilted. FCal noisy. Non-expert Pair Spec. access. Event display freeze.
- •Last accelerator harps not functional.
- •Safety: unorthodox access to hall during Controlled Access.



- •Good radiation levels (both in tagger and Hall) once the beam is tuned. Reproducible. Standard beam delivery procedure established.
- •Rates scale with radiator thickness \Rightarrow Good photon beam. No scrapping.
- •Profiler works.Active collimator works and is calibrated.
- •Transmission through collimator seemed good.
- Beam line (including target) is well aligned. Diagnostic tools checked (Upstream Profiler, Halo Counters, Active Target, Pair Spec, Start Counter).
 Solenoid ran at 1000A happily for a long time.
- All detectors worked well. Detectors triggered in coincidence. DAQ works.
 FDC alignment data (no/low B-field) taken. (Only one target position).

•DAQ rate limited.

•Solenoid trips.

•Beam current drift.

Photon flux in Hall varies a lot.

- •Beam position unstable.
- •Downstream Profiler did not work. Replaced by upstream one.
- •FDC cooling system.
- •SC slightly tilted. FCal noisy. Non-expert Pair Spec. access. Event display freeze.
- •Last accelerator harps not functional.
- •Safety: unorthodox access to hall during Controlled Access.



- •Good radiation levels (both in tagger and Hall) once the beam is tuned. Reproducible. Standard beam delivery procedure established.
- •Rates scale with radiator thickness \Rightarrow Good photon beam. No scrapping.
- •Profiler works.Active collimator works and is calibrated.
- •Transmission through collimator seemed good.
- Beam line (including target) is well aligned. Diagnostic tools checked (Upstream Profiler, Halo Counters, Active Target, Pair Spec, Start Counter).
 Solenoid ran at 1000A happily for a long time.
- All detectors worked well. Detectors triggered in coincidence. DAQ works.
 FDC alignment data (no/low B-field) taken. (Only one target position).
- •DAQ rate limited.
- •Solenoid trips.
- •Beam current drift.
- Photon flux in Hall varies a lot.
- •Beam position unstable.
- •Downstream Profiler did not work. Replaced by upstream one.
- •FDC cooling system.
- •SC slightly tilted. FCal noisy. Non-expert Pair Spec. access. Event display freeze.
- •Last accelerator harps not functional.
- •Safety: unorthodox access to hall during Controlled Access.



- •Good radiation levels (both in tagger and Hall) once the beam is tuned. Reproducible. Standard beam delivery procedure established.
- •Rates scale with radiator thickness \Rightarrow Good photon beam. No scrapping.
- •Profiler works.Active collimator works and is calibrated.
- •Transmission through collimator seemed good.
- Beam line (including target) is well aligned. Diagnostic tools checked (Upstream Profiler, Halo Counters, Active Target, Pair Spec, Start Counter).
 Solenoid ran at 1000A happily for a long time.
- All detectors worked well. Detectors triggered in coincidence. DAQ works.
 FDC alignment data (no/low B-field) taken. (Only one target position).
- •DAQ rate limited.

•Beam current drift.

•Solenoid trips.

- Photon flux in Hall varies a lot.
- •Beam position unstable.
- •Downstream Profiler did not work. Replaced by upstream one.
- •FDC cooling system.
- SC slightly tilted. FCal noisy. Non-expert Pair Spec. access. Event display freeze.
 Last accelerator harps not functional.
- •Safety: unorthodox access to hall during Controlled Access.



- •Good radiation levels (both in tagger and Hall) once the beam is tuned. Reproducible. Standard beam delivery procedure established.
- •Rates scale with radiator thickness \Rightarrow Good photon beam. No scrapping.
- •Profiler works.Active collimator works and is calibrated.
- •Transmission through collimator seemed good.
- •Beam line (including target) is well aligned. Diagnostic tools checked (Upstream Profiler, Halo Counters, Active Target, Pair Spec, Start Counter).
- •Solenoid ran at 1000A happily for a long time.
- •All detectors worked well. Detectors triggered in coincidence. DAQ works.
- •FDC alignment data (no/low B-field) taken. (Only one target position).
- •DAQ rate limited.
- •Solenoid trips.
- •Beam current drift. Photon flux in Hall varies a lot.
- •Beam position unstable.
- •Downstream Profiler did not work. Replaced by upstream one.
- •FDC cooling system.
- •SC slightly tilted. FCal noisy. Non-expert Pair Spec. access. Event display freeze.
- •Last accelerator harps not functional.
- •Safety: unorthodox access to hall during Controlled Access.







A. Deur. GlueX collaboration meeting. 02/19/2015



5 GlueX detectors at work!



A. Deur. GlueX collaboration meeting. 02/19/2015



A. Deur. GlueX collaboration meeting. 02/19/2015

Expected 21 days of solid beam.
We used about 16.5 days of solid beam.
We lost about 2.5 days of good beam (solenoid repairs, configuration changes, etc...).

Good accelerator+Hall D performances while both commissioning.

Data summary (S. Dobbs):

https://halldwebl.jlab.org/cgi-bin/data_monitoring/run_conditions.pl

Total number of useful runs: 809.

Number of "analysis quality" (i.e. for bump hunting, not detector calibration) runs: 97:

- FCAL trigger: 18 runs, 1.6 TB
- BCAL trigger: 28 runs, 4.4 TB
- FCAL+BCAL trigger: 51 runs, 40.0 TB

Total data size:

- EVIO (on tape): 120 TB
- REST: 114 GB

Jefferson Lab Thomas Jefferson National Accelerator Facility Exploring the Nature of Matter

Conclusion



Improvements for Spring 2015 run?

- •Run preparation meetings;
- •Feedback from collaboration.

