Andrew’s Updates

12/5/16

Projects

Wire Stringing

- Get drawings for wire stringing supports to machinist
- Assemble the supports
- String the wires

Gas efficiency

- Run fscheck on backed up drive
- Get fADC running
- Measure gas efficiency of mixtures


.375
.38
1.00
ø.38
ø.38
ø.38
ø.38
2.18
13.00
14.90
1.500
4.60
4.80
1.00
1/8 r
4 plcs.
ø.38
1.750
.375
2.688
1.360
1.313
11.60
13.00
.750
.625
Tap Thru 10-32
1.75
.375
1.80
DRAWN
Andrew
25-Nov-16
CHECKED
QA
MFG
APPROVED
TITLE
SIZE
D
DWG NO
HV Left Brace
REV
SCALE
1 / 2
SHEET 1 OF 1







DRAWN Andrew	25-Nov-16		
CHECKED		TITLE	
QA			
MFG			
APPROVED			
		SIZE D	DWG NO Preamp Left Brace REV
		SCALE 1 : 1	SHEET 1 OF 1


1.00
Ø.375 THRU
1.00
Ø.375 THRU
1.00
Ø.375 THRU
Ø.375 THRU
1.00
.50
4.80
4.80
4.80
.50
8.80
7.30
Drill-thru and
tap 1/4 - 20
7.70
.50
15.40
Use ¼" aluminum plate
All measurements in inches
Pre-amp Support
Support
7.4:4
1 OF 1