
DIRC Environment (as of 11/17)



DIRC Controls To Do

- Finish first REV of PLC GUI –BarBox0 flow/dp
- Vacuum Head Temperature Sensor
- UV Bulb Out Indicators
- Test Comms between platform PLC and Skid PLC

 Ask: DI status, DO status, AI status
 - Write: DO requests/Kill
- Finish Logic for DP/Flow in platform PLC (units?)
- Humidity sensors?
- Order and Install Terminal Blocks/Rack management/Cables

DIRC PLC GUI

