




Carbon tube layout in detector #7 (field wires not shown)











First equal length carbon tube

Last non-equal length carbon tube

Is the carbon tube bond creating a discharge?

