## Simulation & Other Works Update


- Completed installation of simulation software on lab computer
- Currently resolving one simulation issue
- Updating MWPC design files




## **Simulation Issue**

• Events are disappearing

gen\_2mu – creates 2000 muon pair events CPPsim – processes 2000 events mcsmear –processes 193 events hd\_root –processes 192 events




pim\_theta\_Thrown



**Above:** Angle distribution for 2000 muon pair events, from gen\_2mu

**Left:** Angle distribution after processing events through CPPsim, mcsmear, and hd\_root

## **Gathering MWPC parameters**



## **Looking Forward:**

- \* Resolve simulation event issue
- Use simulation to obtain MWPC data (Jordan + Bobby)
- Finish gathering MWPC parameter values
- **❖** Assemble MWPC
- Finalize electronics design