

Status Report

February 14, 2012

Shipping procedure



Stage 2 and 3

- Stage 2
 - Pulse shape of 7 boxes
 - Connectors fails due to mechanical stresses
- Stage 3
 - Condensation inside dark box