


Hall D/ SRC Calibration Flowchart*

Time

Priority

Remaining



TPOL

CCAL

*detectors in blue boxes and connected with an arrow are dependencies