



Live - C1285R12MM sm4102855704







mouse wheel to zoom, left click to pan Help text



















345

325

305

Mirror Machining

- Vendor has a delay and raised a problem 3 weeks after receiving part
 - Talking with them now
 - Considering other vendors/using smaller pieces of mirror
- Planning to test mirrors through remaining machining phases