Update

- Completed 7th wire frame assembly. One more to go
- Need to have Walt drill a 2" dia hole through the center of the 8th set of aluminum plates
- Remainder of this week work on getting tooling in place so that Walt can hang a drill press over the plate.
- Working on the setup of a test chamber that we can bring to JLab for noise studies











